Professional Summary

An experienced contract miner, supervisor and project manager with over 35 years of diversified project experience working at underground mining operations throughout Canada, USA and overseas.

Work History

- 2015 to date Multiurethanes Ltd. Mississauga, ON Multiurethanes Inc. Buffalo, NY
- **1987-2015** Contract mine supervisor and project manager working on numerous underground mining projects.
- **1988-2005** Self-employed grouting contractor working on various civil and mine construction projects in collaboration with Multiurethanes
- **1975-1984** Development miner including shaft sinking and raise mining

Current Safety Certifications

- Standard First Aid CPR-A & AED
- H&S Awareness Supervisor
- Confined Space Entry
- Working at Heights
- WHMIS

Education

1985-1986 Business Management Red River Community College Winnipeg, Manitoba

Specialties

- Control of water inflows and rock grouting applications for underground mines and heavy civil construction projects
- Control of water inflows through leaking concrete structures, construction joints, expansion joints and rock fissures
- Hands on technical experience with cement and chemical grouting operations
- Cement grouting
- Chemical grouting

Technical Skills

- Diversified hands-on expertise in cement grouting solutions for the control of water inflows, leak sealing, and concrete restoration
- Advanced knowledge of grout material selection, including grout formulations and the use of additives
- Training and supervision of contractor personnel for concrete repair and water control applications at underground mines
- Compliant with Norcat training standards and mine specific safety procedures

Selected Grouting Experience



Cement Grouting

Dubreuilville, ON

Onsite grouting specialist for construction of a new vent raise and electrical service hole for a gold mine using diamond drilling and cement grouting.



Buried Tank Decommission Sudbury, ON

Grouting supervisor engaged on a decommission project to fill two large buried tanks located on the Guindon North Dam with a slag-cement-bentonite mixed in a batching plant set up on site.



Consolidation Grouting Sudbury, ON Performed consolidation grouting and liner welding work for construction of a new tailings dam for a mining company in Northern Ontario.



Cement grouting Timmins, ON Implemented a grouting program to improve ground conditions in preparation for the excavation of a new ventilation raise by filling existing open rock fractures with cement.